EMR Corp 6531-0/SB-4 UHF Bandpass Filter
S/N: 150626-015
BandpassAfter Tuning



1:Mkr (MHz) dB	2:Mkr (MHz) dB
1> 466.41 -2.77	

Tuned for Center Freq. of 466.4125 Mhz

I.L. @ 466.4125: 2.77 dB

Services by DuplexerRepair
(334) 444-6796 www.DuplexerRepair.com
(A division of Alabama Broadcast Services, LLC)

EMR Corp 6531-0/SB-4 UHF Bandpass Filter
S/N: 150626-015
Return Loss/VSWR After Tuning



1:Mkr (MHz) dB	2:Mkr (MHz) dB
	1> 466.41 -29.48

RL @ 466.4125: 29.48 dB
VSWR = 1.069:1
Match Efficiency: 99.887%

Services by DuplexerRepair
(334) 444-6796 www.DuplexerRepair.com
(A division of Alabama Broadcast Services, LLC)

EMR Corp 6531-0/SB-4 UHF Bandpass Filter
S/N: 150626-015
Bandwidth & Filter Q After Tuning



1:Mkr (MHz)	dB	2:Mkr (MHz)	dB
1> 0.00	0.00		
3: 0.04	0.00		
5: -1.94	-2.99		
6: 2.01	-3.00		

Services by DuplexerRepair
(334) 444-6796 www.DuplexerRepair.com
(A division of Alabama Broadcast Services, LLC)

EMR Corp 6531-0/SB-4 UHF Bandpass Filter
S/N: 150626-015
*** *Service Photos* ***

Services by DuplexerRepair
(334) 444-6796 www.DuplexerRepair.com
(A division of Alabama Broadcast Services, LLC)