


Telewave TPRD-1556

S/N: 23378

Low Pass Branch Return Loss/SWR After Tuning




1:Mkr (MHz) dB	2:Mkr (MHz) dB
1: 153.46 -1.38	1> 153.46 -30.90
2> 158.27 -103.88	2: 158.27 -0.21
Isolation: 103.88 dB Insertion Loss: 1.38 dB	Return Loss: 30.90 dB VSWR: 1.059:1 Match Efficiency: 99.919%

Services by DuplexerRepair
(334) 444-6796 www.DuplexerRepair.com
(A Service of Alabama Broadcast Services, LLC)

Telewave TPRD-1556

S/N: 23378

High Pass Branch Return Loss/SWR After Tuning



1:Mkr (MHz) dB	2:Mkr (MHz) dB
1> 153.46 -101.08	1: 153.46 -0.24
2: 158.27 -1.44	2> 158.27 -23.31
Isolation: 101.08 dB Insertion Loss: 1.44 dB	Return Loss: 23.31 dB VSWR: 1.147:1 Match Efficiency: 99.533%


Services by DuplexerRepair
(334) 444-6796 www.DuplexerRepair.com
(A Service of Alabama Broadcast Services, LLC)

Telewave TPRD-1556


S/N: 23378

Branch Impedances After Tuning

Low Pass Branch:



High Pass Branch:



Services by DuplexerRepair

(334) 444-6796 www.DuplexerRepair.com

(A Service of Alabama Broadcast Services, LLC)

Telewave TPRD-1556

S/N: 23378

Service Photos



Services by DuplexerRepair
(334) 444-6796 www.DuplexerRepair.com
(A Service of Alabama Broadcast Services, LLC)