


Celwave Model 526-4-2 UHF Duplexer

S/N: 36532

Low Pass Branch Tests After Fine-Tuning




1:Mkr (MHz) dB	2:Mkr (MHz) dB
1: 444.95 -1.17	1> 444.95 -37.88
2> 449.95 -103.41	2: 449.95 0.02
Isolation: 103.41 dB Insertion Loss: 1.17 dB	Return Loss: 37.88 dB VSWR: 1.026:1 Match Efficiency: 99.984%

Services by DuplexerRepair
(334) 444-6796 www.DuplexerRepair.com
(A Service of Alabama Broadcast Services, LLC)

Celwave Model 526-4-2 UHF Duplexer

S/N: 36532

High Pass Branch Tests After Fine-Tuning



1:Mkr (MHz) dB	2:Mkr (MHz) dB
1> 444.95 -104.73	1: 444.95 0.02
2: 449.95 -0.99	2> 449.95 -37.72
Isolation: 104.73 dB Insertion Loss: 0.99 dB	Return Loss: 37.72 dB VSWR: 1.026:1 Match Efficiency: 99.983%

Services by DuplexerRepair
(334) 444-6796 www.DuplexerRepair.com
(A Service of Alabama Broadcast Services, LLC)

Celwave Model 526-4-2 UHF Duplexer

S/N: 36532

Service Photos




Services by DuplexerRepair
(334) 444-6796 www.DuplexerRepair.com
(A Service of Alabama Broadcast Services, LLC)

Celwave Model 526-4-2 UHF Duplexer

S/N: 36532

Service Photos



Services by DuplexerRepair
(334) 444-6796 www.DuplexerRepair.com
(A Service of Alabama Broadcast Services, LLC)